

Owletts Mansion & Outbuildings: Heritage Statement

PROPOSED LISTED BUILDING CONSENT

FOR CONSERVATION REPAIRS TO OWLETTS MANSION & OUTBUILDINGS TO THE EAST AT THE STREET, COBHAM, KENT

Introduction

The proposed works as set out in this Heritage Statement form part of a programme of necessary repair and conservation works to a number of ancillary structures and elements associated with the historic house at Owletts. The works are focused on addressing ongoing deterioration caused primarily by water ingress, material decay and structural movement, whilst ensuring the retention of historic fabric wherever practicable.

The proposals follow established conservation principles of minimal intervention, repair rather than replacement, and the use of appropriate traditional materials and methods to ensure that the character and significance of the heritage asset are preserved.

Site Description

Owletts is a historic country house and estate located in Cobham, Kent. The principal house is Grade II* listed and dates from the late 17th century. This application primarily relates to the repair and conservation of several historic garden outbuildings located to the east of the main house, together with minor associated works to the main house involving alterations to a roof parapet gutter outlet.

The outbuildings form part of the historic walled garden and orchard setting, illustrating the traditional service structures associated with the maintenance and cultivation of the estate gardens. The works relate principally to a potting shed and loggia, which are attached to a tall brick spine wall forming part of the walled garden enclosure. This wall frames a central hedged opening leading into the orchard and kitchen garden beyond.

Further to the east are two greenhouse structures. One greenhouse occupies the corner of the garden wall, while a second greenhouse stands detached nearby as a later addition. Together these structures form part of the historic working garden infrastructure associated with the house.

In addition to the outbuilding repairs, minor works are proposed to the south-east elevation of the main house, where the existing gutter outlet through the parapet will be enlarged to improve rainwater discharge and reduce the risk of water overflow and moisture-related deterioration to the masonry below.

The site lies within the Cobham Conservation Area and the Kent Downs Area of Outstanding Natural Beauty. The surrounding area is rural in character, comprising historic buildings, farmland and scattered residential properties along The Street.



1. South-east elevation of Owletts Mansion



2. View of Loggia structure

Listed Building
Listed Status: Grade II*
List Entry Number: 1049097
Date of Listing: 27-Aug-1952
Statutory Address: Owletts, The Street
Listing Description: Built in 1683/4 by Bonham Hayes. Red brick, moulded brick string course. Panelled parapet added C18. Steeply pitched hipped tiled roof. Narrow end bays project to form closets. Slight central projection. Seven sash windows and 3 dormers. Modern porch with re-set panelled door. Engaged Doric columns, pediment and semi-circular fanlight. Two steps with wrought iron handrails. Two massive panelled chimney stacks dated 1683. Lead downpipes with heads inscribed G.G.1754. Three sash windows and 2 dormers to east and west façades. Large modern single-storey bay to east. Central projection to north facade marking staircase with 2 tall “croise” windows with leaded lights and 3 ox eye windows above. Two projections added by Sir Herbert Baker in 1925 and C19 wing added at north-west corner. Internally fine staircase and plaster ceiling, bolection mouldings to fireplaces and panelling dated from 1684. In 1894 the house passed to the Edmeades family of Nurstead then by marriage to the Baker family until in 1938 Sir Herbert Baker who lived there gave it to the National Trust.
Conservation Area: Yes
Area of Outstanding Natural Beauty: Yes



3. View of Potting Shed structure

Historic Maps

Historic mapping indicates that the garden walls and associated outbuildings to the east of the house have formed part of the site layout since at least the late 19th century. While the main house at Owletts has undergone a number of alterations over time, the current proposals relate primarily to the group of service buildings within the walled garden, including the loggia, potting shed and greenhouse structures.


Early Ordnance Survey maps suggest that the brick garden wall and associated horticultural buildings were already established by the late 19th century, forming part of the working kitchen garden and orchard that historically supported the estate.

The mapping also indicates that these outbuildings have evolved incrementally over time. The loggia and potting shed structures appear to have been extended or modified, reflecting their continued functional use within the gardens. Similarly, the current greenhouse footprint appears substantially larger than that shown on the 1871 Ordnance Survey map, suggesting later enlargement or replacement of earlier structures.

The 1871 mapping further suggests that the brick garden wall may originally have extended further westwards to meet the side of the main house, indicating that the configuration of the garden enclosure has also altered slightly over time.

Overall, the historic mapping demonstrates that the garden wall and its associated outbuildings have long formed an integral part of the historic garden layout, evolving gradually in response to the practical requirements of the estate's horticultural use. The structures therefore contribute to the historic character of the gardens and illustrate the long-standing use of this part of the site for cultivation and garden management.

The below historic phasing plan demonstrates when significant additions or replacements were conducted to the footprint of these structures:



Historic Phasing Assessment Of Outbuildings



Defects and Repairs

Overview

The following sections identify and assess the existing defects and proposed remedial works to the historic garden outbuildings and associated structures at Owletts. For clarity, the works have been categorised by individual structure, namely:

- ≡ Loggia
- ≡ Potting Shed
- ≡ Greenhouse
- ≡ Main House (gutter outlet at roof level)

Each section outlines the observed condition of the structure, the principal defects affecting the historic fabric, and the proposed repairs. The methodology for all repairs is outlined in a latter section within this document. The repairs have been developed in accordance with conservation best practice, prioritising the retention of existing historic fabric where possible, the use of compatible traditional materials, and minimal intervention to ensure the continued longevity of the buildings while preserving their historic character. Structural repairs have been informed where necessary by specialist advice, with non-structural repairs following established conservation techniques appropriate to the materials present.

We also state here the impact on significance:

Higher significance: for example, fabric that relates to its original form, of high architectural merit or importance to the asset.

Medium significance: for example, fabric that is not of extreme importance, some of the original building can be appreciated and there is adequate fabric quality showing the change in the buildings use and style.

Low significance: for example, fabric that displays less historic character and style of the original structure, but contributes to the social narrative and hierarchy of the building.

The proposals are structured and explained as per the following:

Defects – Outlining the main reason for intervention based on a problem associated with the building fabric performance

Repairs – How we intend to deal with the issues.

Recording – How the existing situation will be recorded before work starts.

Architectural and Fabric Significance – An indication of the proposals on the significance.

Loggia

Defects

The loggia structure has experienced significant deterioration to the timber roof structure, primarily due to prolonged exposure to moisture and age-related decay. The existing primary timber beams are severely rotten and structurally compromised, resulting in partial collapse of the roof structure.

Associated defects include cracking within the masonry walls, likely resulting from historic movement and the loss of structural stability caused by the failing roof structure. In addition, areas of spalled brickwork, missing mortar joints and inappropriate historic repairs using hard cement-based mortars have been identified. Vegetation growth and the accumulation of leaves and debris within the loggia have further contributed to moisture retention and ongoing deterioration of the masonry fabric.

Repairs

Structural repairs will be undertaken in accordance with the Structural Engineer’s report and drawings. The existing decayed timber beams will be replaced with six new 200 × 200mm D30 grade oak primary beams, improving structural stability while maintaining a traditional material appropriate to the structure.

In addition, seven timber slats positioned above the primary beams will be replaced with new 100mm × 75mm D30 oak members, matching the existing configuration and dimensions.

Cracked masonry will be stabilised using 6mm diameter Helifix stainless steel reinforcement bars, installed within the bed joints at every third course along the length of the cracks. The installation will involve carefully raking out bed joints to approximately 40mm depth, inserting the reinforcement bars in accordance with manufacturer’s specifications, and repointing the joints with a suitable lime mortar.



1. View of Loggia from south with Owletts Mansion behind



2. View of north west elevation of Loggia



3. View of north west elevation of Loggia and Potting Shed

Areas of missing or deteriorated mortar will be raked out and repointed using a lime mortar matched to the existing through analysis of samples taken from deep within the mortar joints.

Areas of spalled brickwork will be addressed through careful removal and turning of bricks to present a sound face where possible. Where bricks are too deteriorated to reuse, reclaimed bricks will be sourced to match the existing masonry.

Recording

Prior to any works commencing, the existing condition of the structure will be photographically recorded, including the timber roof structure, masonry walls and areas of cracking and deterioration. This record will form part of the project documentation.

Architectural and Fabric Significance

The masonry walls and historic fabric of the loggia are considered to be of medium heritage significance, contributing to the historic garden layout and service structures associated with the house. The proposed works are primarily repair and stabilisation works, and will therefore result in no harm to the significance of the structure, while ensuring its long-term conservation.



4. View of Loggia from south east end showing timber roof collapse and excessive vine growth



5. View of Loggia from above showing timber roof collapse



6. View of Loggia half brick ledge with corinthian decorations



7. View of Loggia showing collapsed timber structure from above

Potting Shed

Defects

The potting shed roof structure has deteriorated due to prolonged exposure to moisture and age-related decay, resulting in significant deterioration of the existing timber rafters. The roof structure is no longer considered structurally reliable and requires replacement. The associated masonry has areas of missing and deteriorated mortar, which has allowed moisture penetration into the wall fabric.

Repairs

The existing mono-pitch roof structure will be carefully dismantled and replaced, with the new structure replicating the original roof form, pitch and arrangement. New structural timbers will be installed to match the size and configuration of the original rafters, ensuring the visual and structural character of the building is maintained. Where possible, existing roof tiles will be retained and reused, preserving historic material fabric. Any additional tiles required will be sourced to match the originals. Areas of deteriorated mortar within the masonry will be carefully raked out and repointed using a lime mortar matched to the existing composition, based on samples taken from deep within the joints.

Areas of brickwork coming away from the spine wall on the gable ends will be carefully dismantled and reconstructed using the original materials.

Recording

The existing structure will be photographically recorded prior to dismantling, with particular attention given to the roof structure, tile arrangement and masonry detailing.

Architectural and Fabric Significance

The potting shed forms part of the historic horticultural infrastructure of the garden, and its surviving fabric is considered to be of medium heritage significance. The proposed works involve like-for-like replacement of deteriorated structural elements, ensuring the continued use and preservation of the building with minimal impact on its heritage significance.



1. North elevation of potting shed



2. South-eastern entrance door to potting shed - timber door frame suffers rot



3. Internal photo showing decayed timber structure and failing tarpaulin



4. North west view of potting shed

Greenhouse

Defects

The existing greenhouse structure has experienced extensive decay to the timber framework, particularly at the base of the walls above the brick plinth and within elements of the roof structure adjacent to the guttering. This deterioration is primarily due to prolonged exposure to moisture and the close proximity of timber elements to ground level.

Due to the extent of decay, the timber structure is no longer capable of effective repair.

Repairs

The existing greenhouse structure will be carefully dismantled and replaced, with the new structure designed to match the architectural character, proportions, window rhythm and overall height of the existing building.

The brick plinth will be raised by several courses, increasing the separation between ground level and the timber structure to improve durability and reduce the risk of future moisture-related decay.

A new plinth detail will incorporate a timber cill positioned above a DPC / leaded brickwork, creating an improved moisture barrier between masonry and timber.

The replacement structure will be constructed from durable timber such as Accoya, chosen for its resistance to decay and long-term performance. The timber framework will be painted white to match the appearance of the existing greenhouse.

Glazing will be replaced with reinforced or shatter-resistant safety glazing to improve durability and ensure visitor safety.

Recording

The existing greenhouse will be photographically recorded prior to dismantling, documenting its form, proportions and relationship to the surrounding garden structures.

Architectural and Fabric Significance

The greenhouse is considered to be of low heritage significance, reflecting its role as a functional horticultural structure within the garden setting and the most recent introduction to the eastern kitchen garden. The proposed replacement will retain the visual character and spatial arrangement of the existing structure, ensuring that the historic garden setting is preserved.



1. Front view of greenhouse



2. Rear view of greenhouse



3. Internal view



4. Internal view - showing broken glass panes highlighted in red

Main House

Defects

The existing gutter outlet through the roof parapet is currently undersized, restricting the efficient discharge of rainwater. This increases the risk of water overflow and moisture penetration into the adjacent masonry, potentially accelerating deterioration of the building fabric.

Repairs

The masonry opening will be carefully widened by approximately 100mm, creating a final opening width of approximately 230mm to improve the efficiency of rainwater discharge.

The existing lead flashing will be temporarily removed to allow the masonry alteration. Once the opening has been widened, the lead flashing will be reinstated and dressed appropriately to maintain a waterproof barrier between the masonry and the rainwater runoff.

The brown lightning conductor cable located adjacent to the outlet will be temporarily detached to allow the works to be undertaken safely and will be reconnected once the works are complete.

Recording

The existing condition of the outlet and surrounding masonry will be photographically recorded prior to commencement of works.

Architectural and Fabric Significance


The proposed works affect a small, functional element of the rainwater drainage system and are considered to have low impact on the architectural significance of the building fabric. The works are intended to improve rainwater management and therefore support the long-term conservation of the historic masonry.



1. South-eastern elevation showing affected gutter outlet



2. Close up of gutter outlet, hopper and downpipe



3. Close up of hopper and downpipe

Methodology of Repairs

The following methodology sets out the general approach to the repair works proposed to the Loggia, Potting Shed, Greenhouse, and minor gutter outlet works to the Main House. It is intended to provide a consistent conservation-led framework for all interventions, while allowing for the specific requirements of each structure and defect type.

All works should be undertaken in accordance with best conservation practice, with the aim of retaining as much historic fabric as possible, limiting unnecessary loss, and ensuring that any replacement or repair is based on a clear understanding of the existing construction. Works should proceed in a careful, phased manner, with recording undertaken before and during intervention, and with replacement materials matched closely to the existing in form, material, and appearance.

1. Pre-Commencement and Recording

Before any repair works begin, each structure should be carefully surveyed and recorded in its existing condition. This should include:

- ≡ a full photographic record of each elevation, internal face, roof structure, junction, and defect area
- ≡ close-up recording of areas of timber decay, cracked masonry, spalled brickwork, missing mortar, cement repairs, failed junctions, and defective rainwater details
- ≡ confirmation of elements to be retained, repaired, dismantled, or replaced
- ≡ where relevant, measured confirmation of existing timber sizes, roof pitch, window rhythm, cill details, and masonry openings

Particular care should be taken to record the existing character and detailing of the greenhouse, potting shed roof, and loggia structure before dismantling or repair, so that reinstatement accurately reflects the existing arrangement.

Before repointing works are specified, a sample of original mortar should be taken from deep within the joint, avoiding later surface repairs, so that the binder, aggregate, colour, and texture can be analysed and matched in the new lime mortar.

2. Site Preparation and Access

- ≡ Works should begin with the careful preparation of the immediate area around each structure. This should include:
- ≡ removal of loose debris, fallen material, vegetation growth, and leaf build-up from around and within the structures
- ≡ temporary protection of adjacent historic fabric, garden features, and surfaces during the course of the works
- ≡ cutting back of planting only where necessary, to be undertaken sensitively and, where appropriate, by a landscape professional
- ≡ provision of safe temporary support to unstable fabric where required before dismantling or repair begins

No sound historic material should be removed unless it has first been inspected and confirmed as beyond practical repair, or where limited removal is necessary to enable structural stabilisation.

3. Defect-Based Repair Methodology

Cracked Masonry Repairs

Where masonry cracking has been identified, the cause and extent of the crack should first be confirmed and any associated loose or unstable material carefully inspected. The repair should then proceed as follows:

- ≡ Carefully rake out the affected bed joints along the length of the crack, generally to a depth of approximately 40mm, taking care not to damage adjacent brick arrises.
- ≡ Clean out the joints of dust and loose debris.
- ≡ Install 6mm diameter Helifix bars or equivalent reinforcement within the prepared bed joints, in accordance with the structural engineer’s recommendations and the manufacturer’s instructions. At the loggia, this is to be carried out at every third course along the length of the affected cracking.
- ≡ Repoint and make good the opened joints using an appropriate lime mortar, matched to the original in composition and appearance.
- ≡ Allow the repairs to cure naturally and protect them from rapid drying, frost, or saturation during the curing period.

This method is intended to stabilise the crack while retaining the existing masonry fabric and minimising disturbance to surrounding historic material.

Incorrect Mortar Repairs and Missing Mortar

Where previous hard cement pointing or patch repairs have been applied, these should be treated as incompatible repairs where they are contributing to decay, trapping moisture, or causing adjacent brick damage.

The repair process should be:

- ≡ Carefully remove inappropriate cement-based mortar by hand, avoiding damage to adjacent brick faces and arrises.
- ≡ Rake out loose, failing, or missing mortar joints by hand to an appropriate depth.
- ≡ Clean the joints thoroughly.

- ≡ Repoint using a lime mortar matched to the original mortar sample, based on material analysis taken from deep within the existing joints.
- ≡ Finish the joints to match the historic profile and appearance of the surrounding work.
- ≡ Protect newly pointed work during curing.

This approach allows the masonry to breathe properly and ensures compatibility with the existing historic brickwork.

Spalled or Damaged Brickwork

Where bricks have become spalled or face-damaged through prolonged moisture exposure, trapped salts, or earlier hard mortar repairs, intervention should be limited to the minimum necessary.

The sequence should be:

- ≡ Assess each damaged brick individually to determine whether it can remain, be turned, or requires replacement.
- ≡ Where feasible, carefully remove and turn bricks so that a sound face is presented externally.
- ≡ Where bricks are too deteriorated to retain, carefully cut out individual units with minimal disturbance to surrounding masonry.
- ≡ Insert reclaimed bricks to match the existing in size, colour, texture, and general appearance.
- ≡ Bed and point replacement bricks in an appropriate lime mortar.

Brick replacement should be localised only to those areas where decay is too advanced for retention.

Replacement of Timber Structural Elements

Where structural timbers are decayed beyond repair, replacement should follow a like-for-like or closely matching approach, using durable and appropriate timber species suited to the structure and its exposure.

The methodology should be:

- ≡ Record the existing timber arrangement, member sizes, junctions, and relationship to adjoining fabric before dismantling.
- ≡ Carefully dismantle only those elements confirmed as unsound or beyond repair.
- ≡ Retain any sound associated historic material wherever possible.
- ≡ Introduce new structural timber members to match the existing layout, dimensions, and form.
- ≡ For the Loggia, this includes:
- ≡ replacement of the rotten primary beams with 6 no. new 200 x 200mm D30 oak beams
- ≡ replacement of 7 no. timber slats above, sized 100mm x 75mm D30 oak, to match the existing arrangement

For the Potting Shed, this includes:

- careful dismantling of the decayed mono-pitch roof structure
- replacement with new structural timbers to match the original roof form, pitch, and arrangement
- retention and reuse of existing tiles wherever possible

For the Greenhouse, this includes:

- complete dismantling of the decayed timber structure where the extent of rot makes local repair impractical
- replacement with a new structure matching the architectural style, window rhythm, proportions, and height of the existing
- use of a durable timber such as Accoya
- painting of the new timber structure white to match the existing appearance

All new timber should be detailed to minimise future moisture retention and to improve durability without altering the established character of the structures.

Greenhouse Plinth and Cill Repairs

Relating to the greenhouse, decay at the base of the timber frame indicates a need to improve the interface between masonry and timber.

The methodology should be:

- Carefully dismantle the decayed timber structure and expose the plinth.
- Repair and extend the brick plinth by raising it by several courses, maintaining consistency with the existing masonry character.
- Introduce a revised plinth detail incorporating a timber cill over leaded brickwork, to form a more robust moisture break between masonry and timber.
- Reconstruct the timber frame above in the same general architectural form as the existing structure.

This approach preserves the visual character of the greenhouse while improving long-term performance.

Glazing Replacement

Where greenhouse glazing is replaced, it should be undertaken after the structural frame has been completed and aligned.

The methodology should be:

- Install the new glazing into the reconstructed frame using an appropriate traditional-looking detail.
- Use reinforced or shatter-resistant glazing to improve durability and public safety.
- Ensure that the glazing pattern reflects the rhythm and appearance of the existing greenhouse.
- Rainwater Goods and Gutter Outlet Alteration

- For the minor works to the main house gutter outlet, the intervention should be limited and precise.

The methodology should be:

- Photograph and record the existing outlet, lead flashing, and adjacent masonry before work begins.
- Carefully detach the brown lightning conductor cable locally to allow safe access.
- Carefully remove the existing lead flashing around the outlet and set it aside for reinstatement or restoration.
- Cut back and widen the outlet opening by approximately 100mm, to create a final opening width of around 230mm.
- Make good the masonry opening neatly and ensure the new profile supports improved water discharge.
- Reinstate and dress the lead flashing to provide a continuous waterproof barrier between the brickwork and rainwater runoff.
- Reattach the lightning conductor cable once the works are complete.

All adjacent historic fabric should be protected during the works, and alteration to the parapet masonry should be confined to the minimum necessary.

4. Reinstatement and Finishing

Following repairs, all disturbed areas should be made good using materials appropriate to the host structure. Reinstatement should include:

- reuse of retained historic materials wherever possible
- accurate reinstatement of roof coverings, timber profiles, glazing pattern, and masonry details
- matching of repaired areas to adjacent historic work without creating visually obtrusive alterations
- ensuring all leadwork, cills, junctions, and drainage details are properly finished to shed water effectively

For the potting shed, retained tiles should be reused as far as practicable, with any additional tiles sourced to match. For the greenhouse, the rebuilt structure should reflect the established appearance of the existing building. For the loggia, replacement structural oak members should sit within the historic masonry framework with minimal visual disruption.

5. Conservation Principles to be Applied Throughout

Across all structures, the following principles should apply throughout the works:

- repair rather than replace wherever practical
- retain historic fabric unless its condition makes retention unviable
- ensure all new work is compatible in material and behaviour with the original construction
- use lime mortar for masonry repairs, matched to the historic mortar
- use reclaimed brick where replacement is required, matched to the existing
- ensure replacement timber follows the existing design, proportions, and arrangement
- minimise intervention to the smallest area necessary to achieve long-term stability and weather protection

- ensure all works are carefully recorded before, during, and after intervention

6. Post-Works Review

On completion, the repaired structures should be inspected to confirm that:

- masonry has been stabilised and properly repointed
- replacement timbers have been correctly installed
- retained historic materials have been reinstated appropriately
- leadwork and rainwater details are functioning effectively
- all repairs are visually and materially consistent with the character of the structures

A final photographic record should be made to document the completed repairs and provide a record of the conservation works undertaken.



Impact on Significance and Justification

The proposed works at Owletts are primarily repair, conservation and maintenance works to a group of historic garden outbuildings and a minor element of the main house drainage system. The interventions have been developed in accordance with established conservation principles, with an emphasis on minimal intervention, repair of existing fabric wherever possible, and the use of appropriate traditional materials and techniques.

The works to the loggia and potting shed focus largely on the repair and replacement of failed structural timber elements and the stabilisation of masonry defects, ensuring the continued structural integrity of the buildings while retaining the majority of the historic masonry fabric. Where replacement materials are required, these will be carefully matched to the existing in material, size and appearance.

The greenhouse structure, which has suffered extensive timber decay, requires replacement due to the extent of deterioration. However, the proposed new structure will replicate the architectural form, proportions and visual character of the existing greenhouse, ensuring that its contribution to the historic garden layout and setting is maintained.

The minor alteration to the gutter outlet on the south-east elevation of the main house is limited in scale and is intended to improve rainwater drainage and reduce the risk of moisture-related damage to the historic masonry. The intervention will involve minimal alteration to the surrounding fabric and will support the long-term preservation of the building.

Overall, the proposals will result in no harm to the significance of the heritage asset. Instead, the works will safeguard the condition of the garden outbuildings and associated structures, ensuring their continued use and contribution to the historic character of the site and its wider setting.

Conclusion

This Heritage Statement has assessed the proposed repair and conservation works to the garden outbuildings and associated elements at Owletts, located within the Cobham Conservation Area and the Kent Downs Area of Outstanding Natural Beauty.

The works relate primarily to the loggia, potting shed and greenhouse structures located within the historic walled garden, together with minor alterations to a rainwater outlet at parapet level on the main house. The proposals have been developed in response to identified defects including timber decay, masonry deterioration, structural instability and inadequate rainwater drainage, all of which pose risks to the continued condition of the buildings if left unaddressed.

The repair strategy follows recognised conservation principles, prioritising the retention and repair of existing historic fabric wherever practicable, the use of traditional and compatible materials, and the replication of original forms where replacement is necessary due to deterioration. Structural interventions have been informed by specialist advice, while masonry and fabric repairs adopt appropriate lime-based repair techniques and carefully matched replacement materials.

Where replacement is required, such as in the case of the greenhouse structure, the proposals seek to retain the architectural character, proportions and function of the existing building, ensuring the continued legibility of the historic garden layout.

Overall, the proposals represent necessary and proportionate conservation works that will secure the long-term stability and use of the outbuildings while preserving their contribution to the historic garden setting. The works will therefore sustain and support the significance of the heritage asset, ensuring that these structures continue to form part of the historic character of the site for the future.



RAW STUDIOS

Architecture + Interior Design

