



Photo 11: Standing on Stonebridge Road looking south-west towards the Ford showroom.



Photo 12: view looking south towards the Shell Garage and Eagle Way in the south of the site.



Photo 13: standing in the southern corner of the Football Ground site adjacent to a general waste storage area.



Photo 14: standing north-west of the Football ground looking west. Evidence of hydrocarbon spills on the gravelled ground which is used for vehicle parking.



Photo 15: standing north-west of the Football Club. Moderate evidence of hydrocarbon spills on the gravelled ground.



Photo 17: standing in the south-eastern corner of the football ground looking south at a car wash at the edge of the red line boundary area on Grove Road. Drained to foul.



Photo 16: View down Grove Road to tyre fitter depot.



Photo 18: view of bus maintenance depot located along the eastern boundary of the site. This area had moderate to high evidence of hydrocarbon staining.



Photo 19: view of entrance into the Keyline merchants comprising storage of building materials. This is located east of the football stadium.



Photo 21: Environment Agency depot located in the centre of the eastern extent of the site.



Photo 20: Environment Agency depot located in the centre of the eastern extent of the site.



Photo 22: A diesel storage tank, protected and double skinned located in the EA depot.