

A VERY LARGE
BEE/WASP NEST
PLUS HISTORIC NESTS

WASHED OUT MORTAR
JOINTS ALONG RIDGE
WHERE EACH RIDGE TIE MEETS THE NEXT ONE

AP:

Acrow props and temporary boards to support floor/landing

Cross hatch indicates interior areas
outside of works

EXISTING TYPICAL

Hatch indicates proposed works under existing roof

Refer to hand marked up drawings in the design & access and Heritage statement

VARIOUS
SHIPPED
XCHIPPED
/SLATES

LEAD ROOF APPEARS TO
BE ONLY FLASHED UP
50MM UNDER SLATES

HRFX03

Indicative of signature

LATH AND PLASTER
CEILING HAS COME
DOWN

HSFX06
H1 Classroom

MAIN ISSUES

- ① WATER IS GETTING IN
 - (A) JUNCTION WITH VALLEY GUTTER
 - (B) RIDGE
 - (C) CHIPPED / SLIPPED SLATES
- ② SOME ROTTEN BARKING BOARDS.
- ③ NO INSULATION
- ④ BEES/WASPS GETTING INTO ROOF VOID
- ⑤ CEILING HAS COLLAPSED
- ⑥ NOT CLEAR HOW ROOF IS VENTILATING ACCEPT THROUGH GAPS IN BARKING BOARDS