






View on tapering vertical crack in retaining wall



Close-up view on crack



Angled view on wall showing lateral movement at vertical crack



View on wall looking to south showing outward lean to wall



View on mortar loss to rear face of wall near to vertical crack



View along top of wall showing proximity of trees and undergrowth

