




- MAIN ISSUES**
- ① WATER IS GETTING IN
 - A) JUNCTION WITH VALLEY GUTTER
 - B) RIDGE
 - C) CHIPPED / SLIPPED SLATES
 - ② SOME ROTTEN BARKING BOARDS.
 - ③ NO INSULATION
 - ④ BEES/WASPS GETTING INTO ROOF VOID
 - ⑤ CEILING HAS COLLAPSED
 - ⑥ NOT CLEAR HOW ROOF IS VENTILATING ACCEPT THROUGH GAPS IN BARKING BOARDS