



View along eastern wall looking to north showing damage to boundary and retaining walls



View on northern end of east wall showing proximity to kindergarten, brick loss, sycamore tree roots and damage caused



View of failed boundary wall at upper level showing lack of restriction and safety protection to any persons



View of failed wall and surviving but weak and unstable boundary wall



View on upper level boundary wall showing short length of undamaged wall



View on unprotected edge where boundary wall has failed



View on unprotected edge from lower ground level



View on length of non-retaining boundary wall at low level towards the Pavillion showing damage to top of wall and outward leaning at mid-distance



Close up view of failed brickwork also showing ground anchor



View on lower tree roots showing damage to retaining wall brickwork



Detailed view on tree root damage and penetration into wall brickwork