

Photo Addendum



Scaffold Collapse Front



Scaffold Collapse Rear

Photo Addendum



Front Chimney Damage



Gable End Wall Damage

Photo Addendum



Front Concrete beam and 1st Floor Concrete Block Wall



Front Concrete beam and 1st Floor Concrete Block Wall

Photo Addendum



Rear Concrete Block Wall 1st Flr



Rear Concrete Block Wall Ground floor

Photo Addendum



Internal Chipboard Wall



Internal Chipboard & Block Wall