

NB Asbestos warning.

The existing fibre cement slates have asbestos content. They should have minimal disturbance and must not be cut or abraded. Broken or obstructing tiles to removed and disposed of in accordance with HSE regulations and guidance.

The windmill is a grade II* listed building. The fabric must be protected at all times and not be damaged by the works. No grinders or sharp abrasives to be used on the brick base of the windmill as these will damage the brickwork. Hand tools and brush applications only.

