

CCTV Survey by Survey Solutions Ltd. (dated 23.05.23) indicate this drainage run as foul water however PTA assume this is a surface water run as per the Southern Water asset plan.