

Conservation Officer Comments:

Looking at the ventilation layout now provided it raises questions about how this will work within ceiling/ Is it cutting through joists? Altering the ceiling line which is unacceptable which is what appears to be proposed. It will be important to know how this affect cornices and architectural details. Normally we ask for chimney stacks to be used to get the vertical risers and they need to agree with us where they are going risers and ventilation dumps. We want to see where the actual plant is/ is it in the roof void or is it being put on the outside? We need cross sections showing how that works. Insufficient details is provided in the ventilation plans. As the building is listed ventilation details are important to ascertain prior to making a decision as these details will confirm how the fabric of the historic building would be impacted.