

The Convent of Mercy - Convent building
Headline Results
Scroll down for final results ▲

Return to results menu

On-site baseline	Habitat units	2.08		
	Hedgerow units	0.00		
	Watercourse units	0.00		
On-site post-intervention (Including habitat retention, creation & enhancement)	Habitat units	2.00		
	Hedgerow units	0.13		
	Watercourse units	0.00		
On-site net change (units & percentage)	Habitat units	-0.07	-3.55%	On-site net gain is less than target set ▲ Zero baseline units - % cannot be calculated
	Hedgerow units	0.13	N/A	
	Watercourse units	0.00	0.00%	

Off-site baseline	Habitat units	0.00		
	Hedgerow units	0.00		
	Watercourse units	0.00		
Off-site post-intervention (Including habitat retention, creation & enhancement)	Habitat units	0.00		
	Hedgerow units	0.00		
	Watercourse units	0.00		
Off-site net change (units & percentage)	Habitat units	0.00	0.00%	
	Hedgerow units	0.00	0.00%	
	Watercourse units	0.00	0.00%	

Combined net unit change (Including all on-site & off-site habitat retention, creation & enhancement)	Habitat units	-0.07		
	Hedgerow units	0.13		
	Watercourse units	0.00		
Spatial risk multiplier (SRM) deductions	Habitat units	0.00		
	Hedgerow units	0.00		
	Watercourse units	0.00		

FINAL RESULTS

Total net unit change (Including all on-site & off-site habitat retention, creation & enhancement)	Habitat units	-0.07	Total net gain achieved is less than target set ▲
	Hedgerow units	0.13	
	Watercourse units	0.00	
Total net % change (Including all on-site & off-site habitat retention, creation & enhancement)	Habitat units	-3.55%	0 baseline units - % cannot be calculated
	Hedgerow units	N/A	
		Watercourse units	0.00%
Trading rules satisfied?	No - Check Trading Summaries ▲		

Unit Type	Target	Baseline Units	Units Required	Unit Deficit	
Habitat units	10.00%	2.08	2.29	0.28	
Hedgerow units	10.00%	0.00	0.00	0.00	No additional hedgerow units required to meet target ✓
Watercourse units	10.00%	0.00	0.00	0.00	No additional watercourse units required to meet target ✓

Input errors/rule breaks present in metric ▲