

Project:	Land adj to Gravesend Veterans Club, Gravesend							BS 5837 2012 Trees in relation to design, demolition and construction-	Surveyed by		OH				
Ref:	24-1818-TSS								Weather		Clear				
Date:	04.09.24								Tagged		No				
Client:	Eddie Powell Ltd														
				Canopy Spread											
Tree No.	Species	Height (m)	Stem Dia (mm)	N	E	S	W	Stems	Height of crown clearance	Age class	Physiological condition problems/comments	Structural condition	Preliminary management recommendations	Estimated remaining contribution years	BS category
T1	Acer pseudoplatanus (Sycamore)	12	400	7	5	2	3	1	2	MA	Fair - Poor shape & form. Ivy on tree. Major deadwood in crown. Tree growing on bank approximately 40cm above proposed development.	Good	None	20-40	C1
T2	Acer pseudoplatanus (Sycamore)	6	210	5	7	1	0	1	1.8	MA	Fair - Poor shape & form. Ivy on tree. Major deadwood in crown. Added to topo, overhanging site. On bank approximately 1m above proposed site.	Poor - Decay at base. Historically felled and decayed main stem with epicormic growth re-establishing.	None	44105	C1
T3	Acer pseudoplatanus (Sycamore)	14	435	6	3	6	4	2	3	MA	Good - Tree growing on bank approximately 80cm above proposed development. Smaller stem 1m west of large stem.	Good	None	40+	B2
T4	Acer pseudoplatanus (Sycamore)	15	400	6	3	6	2	1	3.5	MA	Fair - Low vitality. Major deadwood in crown. Sparse crown. Bark staining on main stem, suspected early Cryptostroma. Tree located on bank approximately 1m above proposed development.	Fair - suspected early Cryptostroma.	None	20-40	C1
T5	Acer pseudoplatanus (Sycamore)	10	280	4	5	5	4	1	2.5	MA	Good - Stem divides above 1.5m.	Fair - Included bark present in fork.	None	20-40	C1

Project:	Land adj to Gravesend Veterans Club, Gravesend							BS 5837 2012 Trees in relation to design, demolition and construction-			Surveyed by		OH				
Ref:	24-1818-TSS										Weather		Clear				
Date:	04.09.24										Tagged		No				
Client:	Eddie Powell Ltd																
				Canopy Spread													
Tree No.	Species	Height (m)	Stem Dia (mm)	N	E	S	W	Stems	Height of crown clearance	Age class	Physiological condition problems/comments	Structural condition	Preliminary management recommendations	Estimated remaining contribution years	BS category		
T6	Prunus 'Kanzan' (Flowering Cherry)	4.5	620	5	3	5	5	1	2.5	MA	Fair - Major deadwood in crown.	Good	None	20-40	B2		
T7	Acer pseudoplatanus (Sycamore)	8	280	4	3	1	2	1	2	MA	Fair - Poor shape & form. Unable to inspect stem due to undergrowth. Exudation on stem.	Fair - Exudation on stem, suspected root dysfunction.	None	20-40	C1		
T8	Acer pseudoplatanus (Sycamore)	6	100	2.5	2	1	1	1	2	Y	Fair - Poor shape & form. Suppressed. Unable to inspect stem due to undergrowth.	Good	None	20-40	C1		
T9	Acer pseudoplatanus (Sycamore)	5	90	1	1	3	1	1	2.5	Y	Fair - Poor shape & form. suppressed. Unable to inspect stem due to undergrowth.	Good	None	20-40	C1		
G1	Laurus nobilis (Bay)	6	400	Varied							MA	Good - boundary group. Group comprised of two multi-stemmed Bay trees, stems combined for DBH. Approximately 11 stems.	Good	None	20-40	C1	