

Project:	Land adj to Gravesend Veterans Club, Gravesend							BS 5837 2012 Trees				Surveyed by		OH						
Ref:	24-1818-TSS							in relation to				Weather		Clear						
Date:	04.09.24							design, demolition				Tagged		No						
Client:	Eddie Powell Ltd							and construction-												
Canopy Spread																				
Tree No.	Species	Height (m)	Stem Dia (mm)	N	E	S	W	Stems	Height of crown clearance	Age class	Physiological condition problems/comments	Structural condition	Preliminary management recommendations	Estimated remaining contribution years	BS category					
T1	Acer pseudoplatanus (Sycamore)	12	400	7	5	2	3	1	2	MA	Fair - Poor shape & form. Ivy on tree. Major deadwood in crown. Tree growing on bank approximately 40cm above proposed development.	Good	None	20-40	C1					
T2	Acer pseudoplatanus (Sycamore)	6	210	5	7	1	0	1	1.8	MA	Fair - Poor shape & form. Ivy on tree. Major deadwood in crown. Added to topo, overhanging site. On bank approximately 1m above proposed site.	Poor - Decay at base. Historically felled and decayed main stem with epicormic growth re-establishing.	None	44105	C1					
T3	Acer pseudoplatanus (Sycamore)	14	435	6	3	6	4	2	3	MA	Good - Tree growing on bank approximately 80cm above proposed development. Smaller stem 1m west of large stem.	Good	None	40+	B2					
T4	Acer pseudoplatanus (Sycamore)	15	400	6	3	6	2	1	3.5	MA	Fair - Low vitality. Major deadwood in crown. Sparse crown. Bark staining on main stem, suspected early Cryptostroma. Tree located on bank approximately 1m above proposed development.	Fair - suspected early Cryptostroma.	None	20-40	C1					
T5	Acer pseudoplatanus (Sycamore)	10	280	4	5	5	4	1	2.5	MA	Good - Stem divides above 1.5m.	Fair - Included bark present in fork.	None	20-40	C1					

Project:	Land adj to Gravesend Veterans Club, Gravesend								BS 5837 2012 Trees			Surveyed by		OH				
Ref:	24-1818-TSS								in relation to			Weather		Clear				
Date:	04.09.24								design, demolition			Tagged		No				
Client:	Eddie Powell Ltd								and construction-									
Canopy Spread																		
Tree No.	Species	Height (m)	Stem Dia (mm)	N	E	S	W	Stems	Height of crown clearance	Age class	Physiological condition problems/comments	Structural condition	Preliminary management recommendations	Estimated remaining contribution years	BS category			
T6	Prunus 'Kanzan' (Flowering Cherry)	4.5	620	5	3	5	5	1	2.5	MA	Fair - Major deadwood in crown.	Good	None	20-40	B2			
T7	Acer pseudoplatanus (Sycamore)	8	280	4	3	1	2	1	2	MA	Fair - Poor shape & form. Unable to inspect stem due to undergrowth. Exudation on stem.	Fair - Exudation on stem, suspected root dysfunction.	None	20-40	C1			
T8	Acer pseudoplatanus (Sycamore)	6	100	2.5	2	1	1	1	2	Y	Fair - Poor shape & form. Suppressed. Unable to inspect stem due to undergrowth.	Good	None	20-40	C1			
T9	Acer pseudoplatanus (Sycamore)	5	90	1	1	3	1	1	2.5	Y	Fair - Poor shape & form. suppressed. Unable to inspect stem due to undergrowth.	Good	None	20-40	C1			
G1	Laurus nobilis (Bay)	6	400	Varied						MA	Good - boundary group. Group comprised of two multi-stemmed Bay trees, stems combined for DBH. Approximately 11 stems.	Good	None	20-40	C1			