

Supporting Photographs - Existing Ceiling Condition

Site	Jeskyns Court, Jeskyns Road, Cobham, Gravesend, DA12 3AL
Application	Listed Building Consent - ceiling removal and like-for-like reinstatement
Applicant	Raymond Ellis
Agent	Home Safe Property Services Limited
Reference	PP-15254293 / DSS 72232236



Photograph 1: Existing condition of the water-damaged lath and plaster ceiling at Jeskyns Court. Photographs show areas of cracking, plaster loss and exposed laths.



Photograph 2: Existing condition of the water-damaged lath and plaster ceiling at Jeskyns Court. Photographs show areas of cracking, plaster loss and exposed laths.



Photograph 3: Existing condition of the water-damaged lath and plaster ceiling at Jeskyns Court. Photographs show areas of cracking, plaster loss and exposed laths.



Photograph 4: Existing condition of the water-damaged lath and plaster ceiling at Jeskyns Court. Photographs show areas of cracking, plaster loss and exposed laths.



Photograph 5: Existing condition of the water-damaged lath and plaster ceiling at Jeskyns Court. Photographs show areas of cracking, plaster loss and exposed laths.



Photograph 6: Existing condition of the water-damaged lath and plaster ceiling at Jeskyns Court. Photographs show areas of cracking, plaster loss and exposed laths.



Photograph 7: Existing condition of the water-damaged lath and plaster ceiling at Jeskyns Court. Photographs show areas of cracking, plaster loss and exposed laths.



Photograph 8: Existing condition of the water-damaged lath and plaster ceiling at Jeskyns Court. Photographs show areas of cracking, plaster loss and exposed laths.



Photograph 9: Existing condition of the water-damaged lath and plaster ceiling at Jeskyns Court. Photographs show areas of cracking, plaster loss and exposed laths.



Photograph 10: Existing condition of the water-damaged lath and plaster ceiling at Jeskyns Court. Photographs show areas of cracking, plaster loss and exposed laths.