



Invicta Arboriculture
Tree and Woodland Consultancy

Arboricultural Condition Report

Shorne Common Rough Perimeter Adjacent
Woodlands Road and The Ridgeway Shorne
Kent

8th December 2022

Mr David Sephton Tech Cert (Arbor. A)

Tel: 01303 266958 | Mobile: 07810 783853 | Email: invictaarb@icloud.com



Visual Tree Assessment.

Location: Shorne Common Rough

Name: Mr D. Sephton

Date: 8th December 2022

Client: Shorne Parish Council

Tree No	Species	GPS Reference (British Grid)	Condition	Recommendations	Work Priority
1	Holly x5	TQ – 69062 70295	Group of five dead and predominantly dead trees adjacent footpath and leaning towards the adjacent property (Vanesta). One of the trees has partially uprooted.	Remove all five trees.	2
2	Ash	TQ – 68976 70140	Predominantly dead roadside tree.	Fell to ground level.	2
3	English Oak	TQ – 68965 70210	Small <i>Ganoderma spp</i> fungal fruiting body (bracket) evident at base of tree on the south western side. Localised hollowing detected at the base of the tree on the south western side within an area measuring 200mm x 200mm with minor decay suspected. All remaining buttresses appear to be structurally sound. No further investigations are currently deemed necessary at present. The tree is currently considered to pose an acceptable risk. The tree was recorded as T6 in the 2020 tree inspection report.	Re-inspect within three years of the date of this report.	N/A
4	English Oak		Large diameter (>50mm) decaying deadwood (branch) above adjacent highway at eight metres above ground level.	Remove dead branch.	2

Work Priority: 1= Urgent (within 24 hours). 2= High Priority (within three months). 3= Medium Priority (within six months).

Site Plan:

