

Appendix A - Site Walkover Photographs



Photographic Plate No. 01: View of the site entrance from the west.



Photographic Plate No. 02: View of northern boundary from the east.



Photographic Plate No. 03: Adblue tank located in the north western corner of the site.



Photographic Plate No. 04: High voltage electricity cabinets in the north western corner of the site.

Project : Site E Dering Industrial Park, Gravesend

Client: Optimus Access Ltd

Site Walkover Photographic Plates

Project No.: PC3447


Date: 18 March 2022



Photographic Plate No. 05: View of the storage area in the south western corner of the site (referenced as Structure C on Figure 2).



Photographic Plate No. 06: View of the surface water drain along the eastern boundary of the site.



Photographic Plate No. 07: View of the scaffold storage area along the eastern boundary of the site.



Photographic Plate No. 08: View of the two tiered modular buildings along the western boundary (referenced as Structure A on Figure 2).



Photographic Plate No. 09: View of the 1000l above ground gas oil tank (bunded) with spill kit along the western boundary.



Photographic Plate No. 10: View of unbunded gas oil drums.



Photographic Plate No. 11: General view of the site to the east.



Photographic Plate No. 12: View beyond the northern boundary.



Photographic Plate No. 13: View of COSHH box containing paint.