

Delegated report 20241049 Appendix 3

Site visit Note: 26 February 2025

The balcony works are almost complete with the need for a railing appearing to be the only outstanding issue. The external facing materials for the walls match with existing (painted render).

Site photographs taken 26 February 2025

