

Sitecheck Assess



Contaminated Land

FURTHER ACTION

Plausible contaminant linkages have been identified at the site. As such, potential liabilities have been identified under the relevant contaminated land legislation. Please refer to the next section for further information.



Flood Risk Screen

NONE IDENTIFIED

We have not identified an elevated flood risk at your property. A full flood risk report is not considered necessary.



Energy & Infrastructure Screen

IDENTIFIED

A screening of Energy & Infrastructure projects has identified a project/s at or close to the property. You should purchase a SiteSolutions Energy & Infrastructure report to better understand the potential impact on the property. Please refer to the next section for further information.



Radon

IDENTIFIED

We have identified that the property is in an area with an elevated probability of radon. Please refer to the next section for further information.



Environmental Constraints

NONE IDENTIFIED

No Environmental Constraints have been identified within 250 metres of your property.

This report is issued for the property described as:
Unit K6, Lower Road, Northfleet, Gravesend, DA11 9BL

Report Reference:
293166087

National Grid Reference:
561410 175020

Customer Reference:
G2732698_SAS

Report Date:
25 March 2022

CONTACT DETAILS

If you require any assistance please contact our customer support team on:

0844 844 9966

or by email at:
helpdesk@landmark.co.uk

Professional Opinion and Recommendations

Please see below our recommendations and next steps. These may be copied into your Report on Title if you wish. No physical site inspection has been carried out or is proposed.



Section 1: Contaminated Land

FURTHER ACTION

Professional Opinion

In the professional opinion of Landmark Information, potential liabilities have been identified under Part 2A of the Environmental Protection Act 1990. To quantify these, you may decide to undertake a more detailed assessment following the recommendation(s) set out below.

You should be aware of the following:

A review of historical mapping has revealed the following historical or current potentially contaminative uses on site: a corn windmill (1864), tramways (1898) and light industrial units (1978).

As part of this assessment, we have considered sensitive receptors and human health, as this information is considered as part of the Local Authorities Part 2A inspection strategy.

Please see section 1 for further information. Alternatively, please contact your professional advisor or Landmark Customer Services on 0844 8449966.

Recommendations

Landmark Information may be able to revise the risk assessment by reviewing additional information. To take advantage of the free re-review service, please forward relevant information to: helpdesk@landmarkinfo.co.uk

This should include:

A written comment from the Environmental Health Department (Local Authority) including the following:

A comment on the Property's potential to be investigated under Part 2A of the Environmental Protection Act, 1990. The comment needs to include whether or not the Property is likely to be investigated under this legislation, if so what priority it has been given, and a reason for this priority status. Please note that Local Authorities can take up to 20 working days to provide this information.

Or, if the Site has recently been redeveloped, planning information may be available from the Planning Department (Local Authority):

Planning permission for the Property including contaminated land conditions, with written confirmation from the Local Authority that these have been fully discharged. Please note, planning permission without contaminated land conditions will not be accepted.

Alternatively, we can collect and review this additional information on your behalf at a cost of £450 + VAT.

If the Property is operational, you should consider undertaking an Environmental Audit in order to investigate current operational environmental liabilities, compliance issues and any historical legacy that the Property owner may be exposed to. We can offer a contaminated land, compliance and other environmental audits from £950 + VAT.

A warranty or similar guarantee, environmental indemnity or Contaminated Land insurance Policy would transfer risk identified in the context of the report, subject to its validity, wording and terms.

Please call 0845 4585250 for further information.

Professional Opinion and Recommendations



Section 2: Flood Risk Screen

NONE IDENTIFIED

Landmark Information have not identified an elevated flood risk at your property. A full flood risk report is not considered necessary.



Section 3: Energy & Infrastructure Screen

IDENTIFIED

Landmark Information have identified Energy or Infrastructure projects at or close to the property. In order to gain more detailed information regarding the projects and the potential impact, it is recommended that you purchase a SiteSolutions Energy & Infrastructure report. If you would like more information, please contact your Search Provider or our Customer Services Team on 0844 844 9966 or email helpdesk@landmark.co.uk.



Section 4: Radon

IDENTIFIED

Landmark Information have identified that the property is in an intermediate probability radon area as between 1 and 3% of homes are estimated to be at or above the action level. This does not necessarily mean that the property has high radon or that there is cause for concern. Public Health England advises that homes in affected areas should be tested. For further information please contact Public Health England (see Contacts section) or go to www.ukradon.org

Radon Protection Measures: No radon protective measures are necessary in the construction of new dwellings or extensions to existing buildings. If you would like more information, please contact your professional advisor or Landmark Customer Services on 0844 8449966.



Section 5: Environmental Constraints

NONE IDENTIFIED

Landmark Information have not identified any environmental constraints within 250m of the property.

Next Steps


If you require any assistance, please contact our Customer Services Team on:
0844 844 9966 or helpdesk@landmark.co.uk

Property Location



Location Plan

The map below shows the location of the property.



Contains Ordnance Survey data © Crown copyright and database right 2022.

◇ Site

○ Search Radii

Property Purchaser Guide



Understanding this report

The purpose of this report is to highlight any potential risk of contaminated land, as defined under Part 2A of the Environment Protection Act 1990. The report also examines whether the property is at risk from other specified environmental factors that may impact the future intended use and saleability of the property.

For contaminated land, we will state 'Passed' on the front page if our environmental consultants consider there to be no risk to the property. If a potential risk of contaminated land is found, the report front page will state 'Further Action'. In this case, we will include our recommendations and next steps.

For all other environmental factors, we will state 'None Identified' if no potential risk is found and 'Identified' if a potential risk is found. In this case, we will provide recommendations or details of further information required to explore this potential risk.

Section 1: Contaminated Land

In this section, we highlight on a map, and within our findings pages, if there are any potential contaminated land risks at or around the property. Contaminated land contains substances that are actually or potentially hazardous to health or the environment.

Section 2: Flood Risk Screen

This section is a flood screen. This means that if we highlight a flood risk at the property, a further report will be required in order to understand the full details and possible impact on the property. Within the section, we consider River, Coastal, Surface water, Groundwater and other flood risks.

Section 3: Energy & Infrastructure Screen

This section is an Energy and Infrastructure projects screen. This means that if we identify any projects at or

close to the property, a further report will be required in order to understand the full details and possible impact on the property. Within the section, we consider projects such as High Speed Rail (HS2), Crossrail 1 & 2, Railways, Southampton to London pipeline, Oil and Gas Exploration (Fracking), & Solar and Wind farms. (only wind and solar farms with a capacity to produce over 1MW of power are considered).

Section 4: Radon

In this section, we identify if the property is located in a radon affected area. Radon is a radioactive gas, which occurs naturally in rocks and soils and may be harmful to health. Employers have duty of care to mitigate the build up of radon gas in higher risk areas.

Section 5: Environmental Constraints

In this section, we identify factors that may have an influence on the property or surrounding area, such as national parks or conservation areas.

Next Steps


If you require any assistance, please contact our customer service team on:
0844 844 9966 or helpdesk@landmark.co.uk

Contaminated Land




Section 1a: Historical Land Uses

The map below shows the location of potentially contaminative historical land uses that have been identified from historical maps and other sources. Further details are shown on the following pages.



Contains Ordnance Survey data © Crown copyright and database right 2022.



Contaminated Land



Section 1a: Historical Land Uses

This section describes historical activity at and around the property, which could be considered to be contaminative. The information is taken from a variety of sources including Landmark's extensive historical map collection and analysis of historic activity. Records are highlighted due to the potential for contamination to exist.

Question	Response
Have any historical potentially contaminative land uses been identified within 250m of the property?	Yes

Map ID	Details	Distance	Contact
Potentially Contaminative Industrial Uses (Past Land Use)			
1	Class: Factory or works - use not specified Map Published Date: 1991	On Site	1
2	Class: Road haulage Map Published Date: 1991	27m	1
3	Class: Factory or works - use not specified Map Published Date: 1946	34m	1
6	Class: Factory or works - use not specified Map Published Date: 1961-1991	95m	1
7	Class: Factory or works - use not specified Map Published Date: 1962-1991	106m	1
9	Class: Factory or works - use not specified Map Published Date: 1991	145m	1
13	Class: Factory or works - use not specified Map Published Date: 1961	196m	1
14	Class: Metal casting/foundries Map Published Date: 1946	212m	1
15	Class: Factory or works - use not specified Map Published Date: 1991	222m	1
Historical Tanks And Energy Facilities			
4	Type: Tanks Date Of Mapping: 1973	54m	1
5	Type: Electrical Sub Station Facilities Date Of Mapping: 1973	76m	1
5	Type: Electricity Industry Facilities Date Of Mapping: 1973	55m	1
5	Type: Electrical Sub Station Facilities Date Of Mapping: 1953	71m	1
5	Type: Electrical Sub Station Facilities Date Of Mapping: 1954	70m	1
10	Type: Tanks Date Of Mapping: 1970	171m	1
11	Type: Tanks Date Of Mapping: 1971	174m	1
12	Type: Tanks Date Of Mapping: 1953	187m	1

Contaminated Land


Map ID	Details	Distance	Contact
16	Type: Tanks Date Of Mapping: 1971	232m	1
17	Type: Tanks Date Of Mapping: 1953	234m	1
17	Type: Tanks Date Of Mapping: 1954	234m	1
18	Type: Tanks Date Of Mapping: 1971	237m	1
19	Type: Tanks Date Of Mapping: 1971	238m	1
Potentially Infilled Land (Non-Water)			
20	Details: Unknown Filled Ground (Pit, quarry etc) Map Published Date: 1994	243m	1
Potentially Infilled Land (Water)			
8	Details: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Map Published Date: 1898	129m	1

Contaminated Land



Section 1b: Incidents and Enforcements

The map below shows the location of land that has been designated as Contaminated Land as well as the locations of other pollution incidents, prosecutions or enforcements. Further details are shown on the following pages.



4

Map ID



Multiple Features Present



Contaminated Land Register Entries and Notices



Environmental Pollution Incidents



Prosecutions Relating to Controlled Waters



Prosecutions Relating to Authorised Processes



Enforcement and Prohibition Notices



Planning Hazardous Substance Enforcements



Local Authority Pollution Prevention and Control Enforcements

Contaminated Land



Section 1b: Incidents and Enforcements

The data within this section tells you whether your property or surrounding area has been identified by the Local Authority as “Contaminated Land” under Part 2A of the Environmental Protection Act 1990 or if there have been any other pollution incidents, prosecutions or enforcements. Should there be an indication of contamination, it is not necessarily a cause for concern. Your report will be assessed by our professional environmental consultants who will advise you what, if any, considerations need to be made should you proceed with the property purchase.

Question	Response
Have any incidents or enforcements been identified within 250m of the property?	Yes

Map ID	Details	Distance	Contact
Contaminated Land Register Entries and Notices No features identified for this property.			
Environmental Pollution Incidents No features identified for this property.			
Prosecutions Relating to Controlled Waters No features identified for this property.			
Prosecutions Relating to Authorised Processes No features identified for this property.			
Enforcement and Prohibition Notices No features identified for this property.			
Planning Hazardous Substance Enforcements No features identified for this property.			
Local Authority Pollution Prevention and Control Enforcements			
21	Reference: B/13/03/rev3 Date of Issue: 5th May 2003 Location: Units P1-2 Northfleet Industrial Estate, Lower Road, Northfleet Details: Not Supplied	170m	2

Contaminated Land



Section 1c: Landfill and Waste Sites

The information in this section identifies active and historical landfill and waste sites within 250 metres of the property. Having a landfill or waste site near your property does not necessarily mean that you or the property will be affected. However, it is something you need to be aware of, because landfill and waste can have a detrimental effect on the surrounding environment, property value and health. A closed landfill/waste site should be given equal consideration to an active site, because of landfill by-products. For instance, landfill with lots of organic material can continue to produce odours and gas for many years.

Question	Response
Have any landfill and waste sites been identified within 250m of the property?	No


Map ID	Details	Distance	Contact
	Historic Landfill No features identified for this property.		
	Registered Landfill Sites No features identified for this property.		
	Local Authority Recorded Landfill Sites No features identified for this property.		
	BGS Recorded Landfill Sites No features identified for this property.		
	Permitted Waste Sites - Authorised Landfill Site Boundaries No features identified for this property.		
	Integrated Pollution Control Registered Waste Sites No features identified for this property.		
	Registered Waste Treatment or Disposal Sites No features identified for this property.		
	Environmental Permitting Regulations - Waste Sites No features identified for this property.		
	Registered Waste Transfer Sites No features identified for this property.		

Contaminated Land



Section 1d: Authorised Industrial Processes

The map below shows the location of any current or recent land uses that could have the potential to cause contamination. Further details are shown on the following pages.



Contains Ordnance Survey data © Crown copyright and database right 2022.

 Map ID	 Fuel Station Entries	 Contemporary Trade Directory Entries
 Multiple Features Present	 Local Authority Pollution Prevention and Controls	 Explosive Sites
 Planning Hazardous Substance Consents	 Control of Major Accident Hazards Sites (COMAH)	 Notification of Installations Handling Hazardous Substances (NIHHS)

Contaminated Land



Section 1d: Authorised Industrial Processes

This section describes current and licensed activities within 250 metres of the property, which have the potential to cause contamination or have an impact on the environment. The licensed activities could range from pollution to air, land or water; or storage of hazardous or explosive materials. Licences may no longer be active, but the nature of the past activity means it could still have an impact.

Question	Response
Have any current or recent authorised industrial processes been identified within 250m of the property?	Yes

Map ID	Details	Distance	Contact
Fuel Station Entries			
42	Name: Shell Northfleet Status: Open Location: Stonebridge Road Eagle Way, Northfleet, Gravesend, Kent, DA11 9BJ Premises Type: Petrol Station	162m	3
Local Authority Pollution Prevention and Controls			
23	Name: Thames Timber Supplies Reference: Pp6/99/046 Date of Issue: 10th January 2000 Location: Area 4, Botany Road, NORTHFLEET, Kent, DA11 9BG Description: PG6/2 Manufacture of timber and wood-based products Status: Authorisation revoked	15m	4
32	Name: C Whenham Reference: B1 Date of Issue: 5th March 1993 Location: Bamber Garage, Northfleet Industrial Estate, Lower Road, GRAVESEND, Kent, DA11 9SR Description: PG1/1Waste oil burners, less than 0.4MW net rated thermal input Status: Authorised	96m	2
35	Name: Marks Demolition Contractors Reference: Pp6/01/048 Date of Issue: 9th November 2001 Location: Grove Road, NORTHFLEET, Kent, DA11 9AX Description: PG3/16 Mobile screening and crushing processes Status: Authorisation certificate surrendered by operator	144m	4
40	Name: Bamber Garage Reference: B/01/99/rev1 Date of Issue: 30th April 1999 Location: Northfleet Industrial Estate, Lower Road, NORHFLEET Description: PG1/1Waste oil burners, less than 0.4MW net rated thermal input Status: Authorisation revoked	161m	2
41	Name: Shell Northfleet Service Station Reference: PP1/98/039 Date of Issue: 30th December 1998 Location: Eagle Way, Stonebridge Way, GRAVESEND, Kent, DA11 9BJ Description: PG1/14 Petrol filling station Status: Authorised	162m	4

Contaminated Land

Map ID	Details	Distance	Contact
46	Name: Barney Sands Ltd Reference: B/13/03/Rev3 Date of Issue: 28th May 2003 Location: Units P1-2 Northfleet Industrial Estate, Lower Road, GRAVESEND, Kent, DA11 9SN Description: PG6/34 Respraying of road vehicles Status: Application exempt from APC	170m	2
47	Name: N T C Lumber (Southern) Ltd Reference: Pp6/95/018 Date of Issue: 8th March 1996 Location: Area 4 Botany Road, Off Lower Road, GRAVESEND, Kent, DA11 9SL Description: PG6/2 Manufacture of timber and wood-based products Status: Authorisation revoked	174m	4
51	Name: Omya Uk Reference: B/07/95 Date of Issue: 30th November 1995 Location: Manor Way, SWANSCOMBE, Kent, DA10 0LH Description: PG3/14 Lime Processes Status: Authorisation revoked	195m	2
55	Name: Cemex Concrete Products Reference: Pp3/02/050 Date of Issue: 12th August 2002 Location: Botany Marshes, Lower Road, NORTHFLEET, Kent, DA11 9BB Description: PG3/1 Blending, packing, loading and use of bulk cement Status: Authorised	207m	4
55	Name: Cemex Concrete Products Ltd Reference: Pp3/92/001 Date of Issue: 22nd March 1993 Location: Off Lower Road, Northfleet, GRAVESEND, Kent, DA11 9AP Description: PG3/1 Blending, packing, loading and use of bulk cement Status: Authorised	231m	4
57	Name: North Kent Commericals Reference: P/24/07/orig Date of Issue: 9th May 2007 Location: Unit 1a Northfleet Industrial Estate, Lower Road, Northfleet, GRAVESEND, Kent, DA11 9SN Description: PG6/34 Respraying of road vehicles Status: Authorised	212m	2
61	Name: Brett Concrete Reference: PP3/92/003 Date of Issue: 26th February 1993 Location: Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Description: PG3/1 Blending, packing, loading and use of bulk cement Status: Authorised	222m	4
61	Name: Cpi Mortars Ltd Reference: PP3/97/021 Date of Issue: 13th March 1998 Location: Robins Wharf, Grove Road, Gravesend, Kent, DA11 9AX Description: PG3/1 Blending, packing, loading and use of bulk cement Status: Authorised	222m	4

Contaminated Land

Map ID	Details	Distance	Contact
66	Name: London Bus And Truck Ltd Reference: Pp6/97/024 Date of Issue: 21st July 1997 Location: Northfleet Industrial Estate, Lower Road, Northfleet, GRAVESEND, Kent, DA11 9SN Description: PG6/34 Respraying of road vehicles Status: Authorised	230m	4
69	Name: North Kent Shotblasting Co Ltd Reference: PP6/92/011 Date of Issue: 2nd August 1994 Location: Grove Road, NORTHFLEET, Kent, DA11 9AX Description: PG6/23 Coating of metal and plastic Status: Authorised	235m	4
Control of Major Accident Hazards Sites (COMAH)			
58	Name: Britannia Refined Metals Limited Status: Active Location: Gravesend, Botany Road, Northfleet, Gravesend, Kent, Da11 9bg COMAH Type: Upper Tier	212m	5
Planning Hazardous Substance Consents No features identified for this property.			
Notification of Installations Handling Hazardous Substances (NIHHS) No features identified for this property.			
Explosive Sites No features identified for this property.			
Contemporary Trade Directory Entries			
22	Name: Thames Steel Processing Ltd Classification: Industrial Services Location: Unit K7, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9BL Status: Inactive	10m	6
24	Name: W E Roberts Classification: Packaging Materials Manufacturers & Suppliers Location: Unit J1, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9BL Status: Active	56m	6
25	Name: Britannia Aggregates Ltd Classification: Sand, Gravel & Other Aggregates Location: Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9BL Status: Inactive	60m	6
26	Name: A A Tyrez Classification: Tyre Dealers Location: Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	61m	6
27	Name: Ccl Veloduct Classification: Air Conditioning Equipment & Systems Location: Unit J5,Northfleet Ind Est,Lower Rd, Northfleet, Gravesend, Kent, DA11 9SW Status: Inactive	67m	6

Contaminated Land

Map ID	Details	Distance	Contact
27	Name: Lindab Ltd Classification: Ventilators & Ventilation Systems Location: Unit J5, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9BL Status: Inactive	69m	6
28	Name: Surestep Specialist Products Classification: Metal Products - Fabricated Location: Unit J2, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9BL Status: Inactive	73m	6
28	Name: Sheet Metal Solutions Classification: Sheet Metal Work Location: Unit J2, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9BL Status: Inactive	73m	6
28	Name: W E Roberts (Packing Supplies) Ltd Classification: Packaging Materials Manufacturers & Suppliers Location: Unit J2, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9BL Status: Inactive	73m	6
28	Name: Metal Kitsch Classification: Tile Manufacturers Location: J2,Northfleet Ind Est,Lower Rd, Northfleet, Gravesend, Kent, DA11 9BL Status: Inactive	73m	6
28	Name: Pelican Fabrications Classification: Joinery Manufacturers Location: Unit J3, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, DA11 9BL Status: Active	69m	6
28	Name: Pelican Fabrications Classification: Joinery Manufacturers Location: Unit J3, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9BL Status: Inactive	69m	6
28	Name: Lindab Kent Ltd Classification: Ventilators & Ventilation Systems Location: Unit 5 Northfleet Industrial Estate,Lower Road, Northfleet, Gravesend, Kent, DA11 9BL Status: Active	88m	6
29	Name: Expert Maintenance Services Ltd Classification: Refrigerators & Freezers - Servicing & Repairs Location: Stonebridge Road, Northfleet, Gravesend, Kent, DA11 9BA Status: Inactive	73m	6
29	Name: Kleeneze Classification: Distribution Services Location: 64, Stonebridge Road, Northfleet, Gravesend, Kent, DA11 9BA Status: Inactive	68m	6
30	Name: Sian Formwork Ltd Classification: Concrete Reinforcements Location: Stonebridge Road, Northfleet, Gravesend, Kent, DA11 9BA Status: Active	82m	6

Contaminated Land

Map ID	Details	Distance	Contact
31	Name: Foice Systems Classification: Electronic Engineers Location: Lake Ho,Northfleet Indust Est,Lower Rd, Northfleet, Gravesend, Kent, DA11 9SR Status: Inactive	93m	6
33	Name: C P P Classification: Plastic Products - Manufacturers Location: Unit K8 Northfleet Industrial Estate,Lower Road, Northfleet, Gravesend, Kent, DA11 9BL Status: Active	99m	6
34	Name: Ebbsfleet Specialist Cars Ltd Classification: Car Dealers - Used Location: Unit A7, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Active	130m	6
36	Name: Swale Motors Ltd Classification: Car Dealers Location: Stonebridge Road, Eagle Way, Northfleet, Gravesend, DA11 9BJ Status: Inactive	145m	6
36	Name: S M C Ford Classification: Car Dealers Location: Stonebridge Road, Eagle Way, Northfleet, Gravesend, DA11 9BJ Status: Active	145m	6
37	Name: Discount Builders Merchants Kent Classification: Builders' Merchants Location: Botany Marsh, Lower Road, Northfleet, Gravesend, Kent, DA11 9BB Status: Active	153m	6
38	Name: J P Commercial Services Classification: Commercial Vehicle Servicing, Repairs, Parts & Accessories Location: Unit 5, Robins Wharf, Grove Road, Northfleet, Gravesend, DA11 9AX Status: Inactive	156m	6
38	Name: Solideal On-Site Service Classification: Tyre Dealers Location: Unit 4, Robins Wharf, Grove Road, Northfleet, GRAVESEND, Kent, DA11 9AX Status: Active	156m	6
38	Name: Monitor Pest Control Ltd Classification: Pest & Vermin Control Location: Unit 3, Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Active	156m	6
38	Name: Golz (Uk) Classification: Diamond Tool Manufacturers Location: Unit 2, Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	156m	6
38	Name: Golz (Uk) Ltd Classification: Diamond Tool Manufacturers Location: Unit 2, Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	156m	6

Contaminated Land

Map ID	Details	Distance	Contact
38	Name: Double D Electronics Ltd Classification: Electronic Engineers Location: Unit 6, Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	156m	6
38	Name: Municipal Vehicle Leasing Ltd Classification: Commercial Vehicle Dealers Location: Unit 5, Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	156m	6
38	Name: Torno Engineering Co Classification: Precision Engineers Location: Unit 4, Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	156m	6
38	Name: M S Repairs Classification: Commercial Vehicle Bodybuilders & Repairers Location: Unit 5, Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	156m	6
38	Name: Grove Storage & Distribution Classification: Road Haulage Services Location: Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	157m	6
38	Name: Set Car Servicing & M O T Centre Ltd Classification: Garage Services Location: UNIT 5, ROBINS WHARF, GROVE ROAD, NORTHFLEET, GRAVESEND, DA11 9AX Status: Active	156m	6
38	Name: Aggregate Industries - Contracting Classification: Sand, Gravel & Other Aggregates Location: Robin'S Wharf,Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	156m	6
38	Name: Aggregate Industries - Asphalt Classification: Sand, Gravel & Other Aggregates Location: Robin'S Wharf,Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Active	156m	6
38	Name: Aggregate Industries Classification: Asphalt & Coated Macadam Laying Contractors Location: Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	156m	6
38	Name: Solideal Classification: Tyre Manufacturers & Distributors Location: Unit 4, Robins Wharf, Grove Road, Northfleet, Gravesend, DA11 9AX Status: Inactive	156m	6
39	Name: Red Route Buses Classification: Bus & Coach Operators & Stations Location: Robins Wharf, Grove Road, Northfleet, Gravesend, DA11 9AX Status: Active	160m	6

Contaminated Land

Map ID	Details	Distance	Contact
43	Name: Shell Classification: Petrol Filling Stations Location: Stonebridge Road, Eagle Way, Northfleet, Gravesend, DA11 9BJ Status: Active	162m	6
43	Name: Priory Motor Group Classification: Car Dealers Location: Stonebridge Road, Eagle Way, Northfleet, Gravesend, Kent, DA11 9BJ Status: Inactive	161m	6
43	Name: S M C Classification: Car Dealers Location: Stonebridge Road, Eagle Way, Northfleet, Gravesend, Kent, DA11 9BJ Status: Active	161m	6
43	Name: Shell (Uk) Ltd Classification: Petrol Filling Stations - 24 Hour Location: Eagle Way ,Stonebridge Rd, Northfleet, Gravesend, Kent, DA11 9BJ Status: Inactive	161m	6
43	Name: Ebbsfleet Cars & Commercial Classification: Car Dealers Location: Eagle Way, Northfleet, Gravesend, Kent, DA11 9BJ Status: Inactive	161m	6
44	Name: North Kent Shot Blasting Co Ltd Classification: Blast Cleaning Location: Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	164m	6
44	Name: Cls Lifting Services Ltd Classification: Lifting Equipment Location: Unit 1, Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	164m	6
45	Name: S T Y Perfumes & Accessories Classification: Perfume Suppliers Location: Unit C5,Northfleet Ind Est,Lower Rd, Northfleet, Gravesend, Kent, DA11 9SW Status: Inactive	167m	6
45	Name: Northfleet Spray & Body Centre Classification: Car Body Repairs Location: Unit A5, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Inactive	156m	6
45	Name: Ebbsfleet Auto Spray Centre Ltd Classification: Garage Services Location: Unit A5, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Inactive	156m	6
45	Name: R S Autocare Classification: Car Body Repairs Location: Unit A5, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Active	156m	6

Contaminated Land

Map ID	Details	Distance	Contact
48	Name: T Weller Classification: Distribution Services Location: Unit R4, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Inactive	185m	6
49	Name: London Distillers Classification: Distilleries Location: Unit 5, Eagle House, Stonebridge Road, Eagle Way, Northfleet, Gravesend, DA11 9BJ Status: Active	193m	6
50	Name: Uk Frictions Ltd Classification: Brake & Clutch Manufacturers Location: P3-P4, Unit, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Inactive	194m	6
50	Name: Gravesham Engineering Services Ltd Classification: Engineers - General Location: P3-P4, Unit, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Inactive	194m	6
50	Name: Ace Car Breakers Classification: Car Breakers & Dismantlers Location: Unit P4, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, DA11 9SN Status: Inactive	195m	6
50	Name: Bamber Garage Ltd Classification: Garage Services Location: Unit P3, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, DA11 9SN Status: Active	192m	6
52	Name: Kentish Minis Classification: Car Dealers - Used Location: 19, Galley Hill Road, Northfleet, Gravesend, Kent, DA11 9BH Status: Inactive	196m	6
53	Name: Brett Concrete Ltd Classification: Concrete & Mortar Ready Mixed Location: Brett House, Grove Road, Northfleet, Gravesend, Kent, DA11 9AY Status: Inactive	199m	6
53	Name: E M R Ltd Classification: Mechanical Engineers Location: Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	202m	6
54	Name: Dutemann Classification: Door Manufacturers - Domestic Location: Unit R3, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, DA11 9SN Status: Active	206m	6
56	Name: Ellis Rees & Co Classification: Metal Finishing Services Location: Grove Road, Northfleet, Gravesend, DA11 9AX Status: Active	209m	6

Contaminated Land

Map ID	Details	Distance	Contact
56	Name: R A Coussens (Castings) Ltd Classification: Foundries Location: Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	209m	6
59	Name: Thameside Transport Services Classification: Road Haulage Services Location: Botany Road, Northfleet, Gravesend, Kent, DA11 9BG Status: Inactive	212m	6
59	Name: Britannia Refined Metals Classification: Metal Products - Fabricated Location: Botany Road, Northfleet, Gravesend, DA11 9BG Status: Active	220m	6
60	Name: Red Route Buses Classification: Bus & Coach Operators & Stations Location: Gramby Coachworks,Grove Rd, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	221m	6
60	Name: Watling Tyre Service Ltd Classification: Tyre Dealers Location: Unit 2, Grove Road, Northfleet, Gravesend, DA11 9AX Status: Active	207m	6
62	Name: Scott Timbre Ltd Classification: Pallets, Crates & Packing Cases Location: Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Inactive	222m	6
62	Name: Brett Aggregates Classification: Sand, Gravel & Other Aggregates Location: Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Active	222m	6
62	Name: Sparrow Crane Hire Ltd Classification: Crane Hire, Sales & Service Location: Gravesend, DA11 9AX Status: Inactive	222m	6
62	Name: C P I Mortars Ltd Classification: Cement Manufacturers & Distributors Location: Robins Wharf, Grove Road, Northfleet, Gravesend, DA11 9AX Status: Active	222m	6
62	Name: C P I Euromix Classification: Mortar Manufacturers Location: Robins Wharf,Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Active	222m	6
62	Name: Brett Concrete Classification: Concrete & Mortar Ready Mixed Location: Robins Wharf, Grove Road, Northfleet, Gravesend, Kent, DA11 9AX Status: Active	222m	6
62	Name: Keyline Civils Specialist Classification: Builders' Merchants Location: Robins Wharf, Grove Road, Northfleet, Gravesend, DA11 9AX Status: Active	222m	6
62	Name: Aggregate Industries Classification: Asphalt & Macadam Suppliers Location: Robins Wharf, Grove Road, Northfleet, Gravesend, DA11 9AX Status: Inactive	222m	6

Contaminated Land

Map ID	Details	Distance	Contact
63	Name: S P J Damp Proofing & Property Maintenance Classification: Damp & Dry Rot Control Location: 18, Taunton Road, Northfleet, Gravesend, Kent, DA11 9BY Status: Inactive	223m	6
64	Name: G B Logistics Plc Classification: Freight Forwarders Location: Unit R2, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Inactive	225m	6
64	Name: Sabotcastle Ltd Classification: Bottle Manufacturers & Suppliers Location: Unit R1, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Inactive	243m	6
65	Name: Scrap Car Gravesend & Medway Classification: Scrap Metal Merchants Location: Unit 1-4, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, DA11 9SN Status: Active	229m	6
65	Name: Chase Garage Kent Ltd Classification: Garage Services Location: Units 1 - 4, Northfleet Industrial Estate, Lower Road, Gravesend, DA11 9SN Status: Active	229m	6
65	Name: Frsh Customs Ltd Classification: Car Customisation & Conversion Specialists Location: Units 1 - 4, Northfleet Industrial Estate, Lower Road, Gravesend, DA11 9SN Status: Active	229m	6
67	Name: V M C Classification: Concrete & Mortar Ready Mixed Location: E1 Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SW Status: Inactive	231m	6
67	Name: Semec Electrical Ltd Classification: Electric Motor Sales & Service Location: Lake House, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, DA11 9SN Status: Active	231m	6
67	Name: North Kent Commercials Ltd Classification: Commercial Vehicle Bodybuilders & Repairers Location: Unit A1, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Inactive	212m	6
68	Name: The Kent Mirror Co Classification: Mirrors & Decorative Glass Location: Unit A6, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Inactive	232m	6

Contaminated Land

Map ID	Details	Distance	Contact
68	Name: Alcatel Cablenet Ltd Classification: Distribution Services Location: Unit C6, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Inactive	232m	6
68	Name: Industrial Metal Services Classification: Metal Workers Location: Unit A7, Northfleet Industrial Estate, Lower Road, Northfleet, Gravesend, Kent, DA11 9SN Status: Inactive	232m	6
70	Name: Ebbsfleet Printing Solutions Classification: Printers Location: Unit 1, Ebbsfleet Business Park, Northfleet, GRAVESEND, Kent, DA11 9DZ Status: Active	245m	6
71	Name: Autofix Classification: Garage Services Location: Unit 7, Ebbsfleet Business Park, Northfleet, Gravesend, DA11 9DZ Status: Active	248m	6
71	Name: Fueltech Classification: Fuel Dealers Location: Unit 7, Ebbsfleet Industrial Estate, Northfleet, Gravesend, Kent, DA11 9DZ Status: Inactive	247m	6
71	Name: Raj Motors Classification: Garage Services Location: Unit 7, Ebbsfleet Industrial Estate, Northfleet, Gravesend, Kent, DA11 9DZ Status: Inactive	247m	6
71	Name: Gtem Classification: Exhaust & Shock Absorber Centres Location: Unit 7, Ebbsfleet Industrial Estate, Northfleet, Gravesend, Kent, DA11 9DZ Status: Inactive	247m	6
71	Name: Gravesend Tyre & Exhaust Mart Classification: Tyre Dealers Location: Unit 7, Ebbsfleet Industrial Estate, Northfleet, Gravesend, Kent, DA11 9DZ Status: Inactive	247m	6

Next Steps

If you would like any further information in respect of the above findings, we recommend that you contact our Customer Services Team on **0844 844 9966** or helpdesk@landmark.co.uk. Further Information is also available in the 'Useful Information' section.

Flood Risk Screen



Section 2a: River and Coastal Flooding

River flooding occurs when rivers and streams are unable to carry away floodwaters within their usual drainage channels. River flooding can cause widespread and extensive damage because of the sheer volume of water.

Coastal flooding results from a combination of high tides, low lying land and sometimes stormy conditions. Coastal flooding can cause widespread and extensive damage because of the sheer volume of water.

Question	Response
Is there a potential risk of river or coastal flooding at the property?	No



Section 2b: Surface Water Flooding

Surface water flooding is common during prolonged or exceptionally heavy downpours, when rainwater does not drain away into the normal drainage systems or soak away into the ground.

Question	Response
Is there a potential risk of surface water flooding at the property?	No



Section 2c: Groundwater Flooding

Groundwater flooding generally occurs during long and intense rainfall when underground water levels rise above surface level. Groundwater flooding may last for weeks or several months.

Question	Response
Is there a risk of groundwater flooding at the property?	No



Section 2d: Other Flood Risks

We analyse any historic flood events records, the proximity of the property to surface water features and the elevation of the property above sea level to enhance our overall analysis of the property.

Question	Response
Are there other flood risks identified that could impact the property?	No

Next Steps

If you would like any further information in respect of the above findings, we recommend that you contact our Customer Services Team on 0844 844 9966 or helpdesk@landmark.co.uk.

Energy and Infrastructure Screen



Section 3a: Oil and Gas Exploration and Production

Any areas to be explored for their energy potential by the oil & gas industry must be licensed by the Oil and Gas Authority. Such exploration includes areas subject to hydraulic fracturing ("fracking") investigation.

Question	Response
Is the property within 4km of any licences or drilling wells that could indicate that onshore oil and gas exploration and production operations are or could happen in the area?	No



Section 3b: Existing or Proposed Wind Farms and Wind Turbines

Wind energy is one of several alternative energy sources; however, the location of wind farms or turbines can be contentious due to visual and auditory impact on the surrounding area. The information in this section gives insight into whether there are wind farms or turbines (planned or existing) in the vicinity of the report location. We only search those wind power developments which generate between 1MW and 50MW of power.

Question	Response
Is the property within 4km of existing or proposed wind farms or wind turbines?	Yes



Section 3c: Existing or Proposed Solar Farms

Solar energy is one of several alternative energy sources; however, the location of a solar farm can be contentious due to its visual impact on the surrounding area. The information in this section gives insight into whether there are solar farms (planned or existing) in the vicinity of the report location. We only search those solar developments which generate between 1MW and 50MW of power.

Question	Response
Is the property within 2km of existing or proposed solar farms?	No



Section 3d: Other Renewable Power Plants

As well as wind and solar power there are a variety of other renewable power sources in the UK. This section identifies planning applications associated with these other types of renewable energy (BEIS only provides data relating to developments which have a capacity to generate over 1MW of power).

Question	Response
Is the property within 2km of any other existing or proposed renewable power plant?	No

Energy and Infrastructure Screen



Section 3e: Infrastructure

This section identifies if there are any Infrastructure projects, such as the High Speed 2 Rail Link (HS2), Crossrail, railways or the Southampton to London pipeline at or close to the property. HS2 is a proposed railway line between London and the North of England. Trains along this route will operate at speeds of up to 250mph. Proximity to the route is likely to have an impact on the surrounding areas. The Crossrail 1 project is a rail project stretching from Reading and Heathrow in the west to Shenfield and Abbeywood in the east. It will improve journey times across London, ease congestion and improve connections. Crossrail 2 is a new (proposed) railway, linking the national rail networks in and around Surrey and Hertfordshire via an underground tunnel through London.

Question	Response
Is the property located in an area that could be impacted by the development of either HS2, Crossrail 1 or Crossrail 2?	No
Is the property located in proximity to railway tracks?	No
Is the property located in proximity to railway stations?	No
Is the property located in proximity to the Southampton to London pipeline route?	No

Next Steps

We have identified energy or infrastructure projects that may impact the property. We recommend you purchase a SiteSolutions Energy & Infrastructure report to gain further information on the type and location of the project. Please contact your Search Provider or our Customer Services Team on **0844 844 9966** or email helpdesk@landmark.co.uk.



Section 4: Radon Findings

The information within this section tells you whether the property is located in a radon affected area. Radon is a radioactive gas which occurs naturally in rocks and soils. You cannot see, hear, feel or taste it. Exposure to particularly high levels of radon may increase the risk of developing lung cancer, and is therefore something you need to be aware of.

Question	Response
Is the property in a radon affected area?	The property is in an Intermediate probability radon area (1 to 3% of homes are estimated to be at or above the Action Level).
What level of radon protection measures for new dwellings or extensions to existing ones is required for the property?	No radon protective measures are necessary in the construction of new dwellings or extensions to existing buildings.

Next Steps

The Ionising Radiation Regulations, 1999, require employers to take action when radon is present above a defined level in the workplace. Advice may be obtained from your local Health and Safety Executive Area Office or the Environmental Health Department of your local authority. The Building Research Establishment (BRE) publishes a guide (BR293): Radon in the workplace. Advice on radon in the workplace can be obtained from the Public Health England.

For further information, please contact Public Health England (see Contacts section) or go to www.ukradon.org.

Environmental Constraints



Section 5: Environmental Constraints

This section provides information on areas which have been designated as having environmental or historical importance; as such there may be constraints on property or land developments or alterations.

Question	Response
Is the property within 250m of an area likely to be impacted by Environmental Constraints?	No

Details	Distance	Contact
National Nature Reserves No features identified for this property.		
Local Nature Reserves No features identified for this property.		
Marine Conservation Zones No features identified for this property.		
Sites of Special Scientific Interest No features identified for this property.		
Ramsar Sites No features identified for this property.		
Special Areas of Conservation No features identified for this property.		
Special Protection Areas No features identified for this property.		
Nature Improvement Areas No features identified for this property.		
Environmentally Sensitive Areas No features identified for this property.		
World Heritage Sites No features identified for this property.		
Ancient Woodland No features identified for this property.		
Country Parks No features identified for this property.		
Areas of Outstanding Natural Beauty No features identified for this property.		
Forest Parks No features identified for this property.		
National Parks No features identified for this property.		

Next Steps

If you would like any further information in respect of the above findings we recommend that you contact our Customer Services Team on 0844 844 9966 or helpdesk@landmark.co.uk.

Useful Information

Limitations and Terms & Conditions

This report has been published by Landmark Information Group Limited ("Landmark") and is supplied subject to our Terms and Conditions of Business, which can be found at <http://www.landmarkinfo.co.uk/Terms/Show/534>. It has been prepared on the understanding that it is to be used for an individual commercial property transaction and should not be used or relied on upon in a residential property transaction. This report is neither a guarantee of the physical condition of the subject property nor a substitute for any physical investigation or inspection. Whilst every effort is made to ensure the details in the report are correct, Landmark cannot guarantee the accuracy or completeness of such information or data, nor identify all the factors that may be relevant. If you are a private individual using this report Landmark recommends that you discuss its contents in full with your professional advisor.

Copyright Statement

The data supplied for this Sitecheck Assess report falls under the following copyrights: Contains Historic Environment Scotland and Ordnance Survey data © Historic Environment Scotland - Scottish Charity No. SC045925 © Crown copyright and database right 2017; Contains Natural Resources Wales information © Natural Resources Wales and database right; Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Contains Ordnance Survey Data. Ordnance Survey Licence number 100019741. Crown Copyright and Database Right; Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Some features of this information are based on digital spatial data licensed from the Centre for Ecology & Hydrology © NERC (CEH). Defra, Met Office and DARD Rivers Agency © Crown copyright. © Cranfield University. © James Hutton Institute. Contains OS data © Crown copyright and database right 2022. Land & Property Services © Crown copyright and database right; Contains public sector information licensed under the Open Government Licence v3.0; Contains, or is based on, information supplied by the Forestry Commission. © Crown copyright and database right 2022 Ordnance Survey [100021242] ; Copyright© 2022 Scottish Environment Protection Agency (SEPA); Designated Historic Asset GIS Data, The Welsh Historic Environment Service (Cadw), 2022, licensed under the Open Government Licence <http://www.nationalarchives.gov.uk/doc/open-government-licence/version/3/>; Flood data provided by JBA Risk Management Limited. © Copyright JBA Risk Management Limited 2008-2022; Ordnance Survey © Crown copyright and/or Database Right. All rights reserved. Licence 100022432 ; Some of the responses contained in this section are based on data and information provided by the Natural Environment Research Council (NERC) or its component bodies the British Geological Survey (BGS). Your use of any information contained in this report which is derived from or based upon such data and information is at your own risk. Neither NERC, BGS nor Public Health England where applicable, gives any warranty, condition or representation as to the quality, accuracy or completeness of such information and all liability (including liability for negligence) arising from its use is excluded to the fullest extent permitted by law; © Crown Copyright and Landmark Information Group Limited 2022. All rights reserved; Contains NatureScot information licensed under the Open Government Licence v3.0; © Environment Agency and database right 2022 ; © Experian Ltd 2022; © GeoSmart Information Ltd; © Historic England 2022. Contains Ordnance Survey data © Crown copyright and database right 2022; © RenewableUK 2022; © Thomson Directories Ltd 2022; ©Landmark Information Group and/or its Data Suppliers 2022; © Natural Resources Wales & United Kingdom Research and Innovation 2022; © Environment Agency & United Kingdom Research and Innovation 2022.

Landmark works in association with:



Useful Contacts

Please see below the contact details of the suppliers referred to within this report. For all queries please contact:

Landmark Information Group
Imperium
Imperial Way
Reading
RG2 0TD

If you require assistance please contact our customer services team on:

0844 844 9966

Or by email at:

helpdesk@landmark.co.uk

Contact	Name	Address	Contact Details
	Public Health England	Centre for Radiation Chemical and Environmental Hazards Chilton Didcot Oxon OX11 0RQ	T: 01235 822622 F: 01235 833891 E: radon@phe.gov.uk W: www.ukradon.org
1	Landmark Information Group Limited	Imperium Imperial Way Reading Berkshire RG2 0TD	T: 0844 844 9966 E: helpdesk@landmark.co.uk W: www.landmark.co.uk
2	Dartford Borough Council, Environmental Health Department	Civic Centre Home Gardens Dartford Kent DA1 1DR	T: 01322 343233 W: www.dartford.gov.uk
3	Catalist Ltd, Experian	Richmond House 22 Richmond Hill Clifton Bristol Avon BS8 1BA	T: 0117 923 7113 E: Mark@catalist-uk.com
4	Gravesham Borough Council, Environmental Health Department	Civic Centre 132 Windmill Street Gravesend Kent DA12 1AU	T: 01474 337241 E: glyn.thomson@gravesham.gov.uk W: www.gravesham.gov.uk

Useful Contacts

Contact	Name	Address	Contact Details
5	Health and Safety Executive	5S.2 Redgrave Court Merton Road Bootle L20 7HS	W: www.hse.gov.uk
6	Thomson Directories	Thomson House 296 Farnborough Road Farnborough Hampshire GU14 7NU	T: 01252 390025 W: www.thomsonlocal.com
7	British Geological Survey, Enquiry Service	British Geological Survey Environmental Science Centre Keyworth Nottingham Nottinghamshire NG12 5GG	T: 0115 936 3143 E: enquiries@bgs.ac.uk W: www.bgs.ac.uk

Please note that if you choose to contact any of the above organisations, they may have a charging policy in place for enquiries.

Useful Information

Information for Professional Advisers

This report is designed to satisfy the concerns raised by the Law Society Practice Note and has been prepared to assist conveyancing professionals who may be advising clients when they sell or buy a property. It is designed to bring information to their attention and help them decide whether they need to seek any further specialist advice. The report gives details of any issues that we have identified as affecting the property or located nearby, and our recommendations on what to do in relation to these issues. You are authorised to copy the recommendations on the Professional Opinion and Recommendations page into any report on title that you provide to your client.

Other Information

Positional Accuracy

We locate data in a variety of ways according to information provided to us and subsequent in-house research. If data is provided as a point on the ground, we provide a "positional accuracy" which tells you how confident we are of the actual location.

Landfill and Waste

At present no complete national data set exists for landfill site boundaries, therefore, a point grid reference, provided by the data supplier, is used for some landfill sites. In certain cases the point grid references supplied provide only an approximate position, and can vary from the site entrance to the centre of the site. Where the exact position of the site is unclear for Registered Landfill data, Landmark construct either a 100 metre or 250 metre buffer around the point to warn of the possible presence of landfill. The size of this 'buffer' relates to the positional accuracy that can be attributed to the site. For further information regarding landfill sites identified in the report, please contact the relevant agency or authority referenced in the Useful Contacts section.

The BGS holds records of over 3,000 landfill sites that accepted waste prior to the Control of Pollution Act (COPA) 1974. These were not subject to any strict regulation or monitoring.

Permitted Waste Sites and Environmental Permitting Regulations - Waste cover current or recently current consents issued for landfill sites, waste transfer, treatment or disposal sites by the relevant agency, under Section 64 of the Environmental Protection Act 1990 (Part 2) and prescribed by regulation 10 of SI No. 1056 of the Waste Management Licensing Regulations 1994.

Authorised Industrial Processes

Data supplied for Explosive Sites, Control of Major Accident Hazards Sites (COMAH) and Notification of Installations Handling Hazardous Substances (NIHHS) contains public sector information published by the Health and Safety Executive and licensed under the Open Government Licence.

Historical Land Uses

This section relates to categories of potentially contaminative land uses that have been identified by the analysis of selected Ordnance Survey historical mapping. The published date (range of dates) of the map(s) and the distance from the centre of search to the nearest point of the feature is given. Further details of the extent of the site or its activities are not available. Should you wish to examine the Ordnance Survey maps these are normally available for public inspection at the local archive or local major library. Alternatively, extracts of editions of Ordnance Survey maps are available on www.old-maps.co.uk

Potentially infilled land has been identified when a 'cavity' (a hole made by an extractive industry or natural occurrence e.g. pond) was indicated on a historic map but there was no evidence of its existence in the last available map for the area. No details of what may have been used to fill the cavity or exactly when or if it was filled are available from the mapping.

The point locations of historical tanks and energy facilities are identified from the text on Ordnance Survey 1:1250 and 1:2500 scale mapping published between 1943 and 1996, based upon a predetermined list of abbreviations, e.g. El Sub (Electricity Sub-station) and F Stn (Filling Station). The position of the point has been located at the centre of the identified text so that it would be within approximately 30 meters of the feature it was describing. The features themselves are related to energy and petroleum storage and cover the following: tanks, petrol storage, potential tanks

Useful Information

(at depots etc.), electricity sub stations and related features, gas and gas monitoring related features, oil related features and miscellaneous power features. NB: It should be noted that the Ordnance Survey abbreviation for tank (tk) is the same as that for tracks. Therefore some of the captured text may relate to tracks and not tanks when the exact nature of the feature is not clear from the mapping.

Other Information

Radon

Radon is a natural radioactive gas, which enters buildings from the ground. It is the geological conditions in certain areas that can lead to higher than average volumes (some of the highest radon levels have been found in the southwest, but levels well above average have been found in some other parts of the UK).

Radon has no taste, smell or colour and special devices are needed to measure it. The gas is diluted to harmless levels out in the open but has the potential to build up to higher concentrations indoors. Exposure to high concentrations of Radon gas can pose a health risk and studies have shown that it increases the risk of lung cancer.

This report informs you whether the property is in a radon Affected Area and the percentage of homes that are estimated to be at or above the radon Action Level. This does not necessarily mean there is a radon problem in the property; the only way to find out whether it is above or below the Action Level is to carry out a radon measurement in an existing property. Due to the nature of the way the information is gathered, your property/site may have more than one probability of radon attributed to it. We report the worst case scenario on the property/site you have provided. This information is an estimate of the probability that a property/site in Great Britain is at or above the "Action Level" for radon (the level at which Public Health England recommends that radon levels should be reduced, those with an average of 200 Bq m⁻³ or more). This information satisfies CON29 Standard Enquiry of Local Authority; 3.13 Radon Gas: Location of the Property in a Radon Affected Area. Where the property/site is a new build, this information provides information on the level of protection required for new buildings under BR211 (Sciwyer, 2007).

Disclaimer: "Some of the responses contained in this section are based on data and information provided by the Natural Environment Research Council (NERC) or its component bodies the British Geological Survey (BGS). Your use of any information contained in this report which is derived from or based upon such data and information is at your own risk. Neither NERC, BGS nor Public Health England where applicable, gives any warranty, condition or representation as to the quality, accuracy or completeness of such information and all liability (including liability for negligence) arising from its use is excluded to the fullest extent permitted by law.

Environmental Constraints

The Local Nature Reserves national dataset is "indicative" not "definitive". Definitive information can only be provided by individual local authorities and you should refer directly to their information for all purposes that require the most up to date and complete dataset.

Crossrail 2

Data sourced from consultation documents as published by the Department of Transport.

Important Consumer Protection Information

This search has been produced by Landmark Information Group Ltd, Imperium, Imperial Way, Reading, Berkshire, RG2 0TD.

Tel: 0844 844 9966

Fax: 0844 844 9980

Email: helpdesk@landmark.co.uk

Landmark adheres to the Conveyancing Information Executive (CIE) standards.

The Standards:

- Conveyancing Information Executive Members shall act in a professional and honest manner at all times in line with the Conveyancing Information Executive Standards and carry out the delivery of the Search with integrity and due care and skill.
- Compliance with the Conveyancing Information Executive Standards will be a condition within the Conveyancing Information Executive Member's Terms and Conditions.
- Conveyancing Information Executive Members will promote the benefits of and deliver the Search to the agreed standards and in the best interests of the customer and associated parties.
- The standards can be seen here: <http://www.conveyinfoexec.com>

Complaints

If you have a query or complaint about your search, you should raise it directly with the search firm, and if appropriate ask for any complaint to be considered under their formal internal complaints procedure. If you remain dissatisfied with the firm's final response, after your complaint has been formally considered, or if the firm has exceeded the response timescales, you may refer your complaint for consideration under The Property Ombudsman scheme (TPOs). The Ombudsman can award up to £5,000 to you if the Ombudsman finds that you have suffered actual financial loss and/or aggravation, distress or inconvenience as a result of your search provider failing to keep to the Standards.

Please note that all queries or complaints regarding your search should be directed to your search provider in the first instance, not to TPOs.

TPOs Contact Details:

The Property Ombudsman scheme
Milford House
43-55 Milford Street
Salisbury
Wiltshire SP1 2BP

Tel: 01722 333306

Fax: 01722 332296

Website: www.tpos.co.uk

Email: admin@tpos.co.uk

Landmark Complaints Procedure

If you want to make a complaint to Landmark, we will:

- Acknowledge it within 5 working days of receipt
- Normally deal with it fully and provide a final response, in writing, within 20 working days of receipt
- Keep you informed by letter, telephone or e-mail, as you prefer, if we need more time
- Provide a final response, in writing, at the latest within 40 working days of receipt
- Liaise, at your request, with anyone acting formally on your behalf

Complaints should be sent to:

Customer Relationships Manager
Landmark Information
Imperium
Imperial Way
Reading
RG2 0TD

Tel: 0844 844 9966

Email: helpdesk@landmark.co.uk

Fax: 0844 844 9980

If you are not satisfied with our final response, or if we exceed the response timescales, you may refer the complaint to The Property Ombudsman Scheme (TPOs):

Tel: 01722 333306

Email: admin@tpos.co.uk

We will co-operate fully with the Ombudsman during an investigation and comply with his final decision.